


Pai

SPARE PARTS LIST for No. 5 REWINDER






rt No.	Description
1	Geared end. Casting
2	Auxiliary end. Casting
3	On/Off plate
4	Centre boss for On/Off plate
5	Brass adaptor for On/Off plate
6	Geared end plate
7	Film keep bar
8	Small gear spindle
9	Large gear
10	Locking arm for film keep
11	Crank handle
12	Auxiliary end spindle
13	Base board for rewinder (not illustrate

NOTE When ordering, please state whether spindles are $\frac{5}{16}$ ", $\frac{3}{8}$ ", $\frac{1}{2}$ " or 9 mm.

EMB

SPARE PARTS LIST for No. 5 REWINDER





Part No. Description	Part No. Description		
6 Geared end plate	9D Pin for large gear spindle		
7 Film keep bar	10 Locking arm for film keep		
7A Plastic knob for film keep	10A Screw and washer for Part No. 10		
7B Retaining spindle for Part No. 7	11 Crank handle		
7C Spindle nut for Part No. 7	11A Plastic handle		
7D Spring and washer for Part	11B Bolt for handle		
No. 7	11C Set of locking nuts and washers		
7E Collar and screw for Part	for handle		
No. 7	12 Auxiliary end spindle		
8 Small gear spindle	12A Split locking nut for Part		
8A Small gear	No. 12		
8B Collar and locking pin for	12B Screw for split locking nut		
small gear	12C Tension adjustment nut for		
8C Locking pin for driving plate	Part No. 12		
8D Driving plate	12E Spring for Part No. 12		
8E Driving pins for driving plate	12F Clutch plate for Part No. 12		
9 Large gear	12G Leather clutch for Part No. 12		
9A Bolts and washers for Part	12H Locking pin for clutch plate		
No. 9	121 Locking pin for driving plate		
9B Spindle for Part No. 9	12J Driving plate		
9C Screw and washer for large	12K Driving pins for Part No. 12J		
gear spindle			

NOTE

When ordering, please state whether spindles are $\frac{5}{16}$ ", $\frac{3}{8}$ ", $\frac{1}{2}$ " or 9 mm.