




### LEGEND

- A2 - Arc current meter
- B2 - Beam terminal Board
- B3 - Lamphouse terminal board
- F4 - Arc current fuse
- I8 - Carbon feed motor switch
- I9 - Lamphouse lighting switch
- I11 - Mascarini safety device switch on lamphouse
- I12 - Arc extract motor switch
- L5 - Lamphouse lighting lamp
- M4 - Carbon feed motor
- M5 - Lamphouse, SuperZenith 450 fan motor
- R3 - Carbon feed motor control resistor

Drn. *W. M. S.*

Date 30/7/63

*V. M. S.*

SUPERZENITH 450 ARC LAMP

Wiring diagram extract motor switch

CINEMECCANICA s.p.a.

Drg. 5569